

OEM-Quality Euro & Asian Metal Base Signal Bulbs

Finest German & Japanese Quality • (E1) Approved
Non-corroding Nickel Plated Bases

European and Japanese vehicles use bulbs that can be tough to find in North America. Similar American-type bulbs may seem to fit and work, but the wrong bulbs can cause socket corrosion and serious problems with the vehicle's electrical system. Many vehicles have bulb outage warning systems that require bulbs of precisely the correct wattage. The trouble caused by incorrect bulbs can seem completely unrelated. For example, if American-type brake light bulbs are installed in certain German cars, the cruise control stops working. To assure customer satisfaction and prevent wasted diagnostic time, specify signal bulbs from Candlepower. They're precision-engineered and built in Germany and Japan to rigid OEM quality standards with top grade materials, and carry the (E1) Type Approval mark, where applicable—the toughest approval mark to get, and your assurance that these bulbs don't just fit, they match!


| bulb type | order number | power (Volts) | power (Watts) | base (ECE) | base (USA) |
|---------------|--------------|---------------|---------------|------------|------------------|
| P21/5W | 17916 | 12 | 21/5 | BAY15d | DC bayonet index |
| P21/4W | 17881 | 12 | 21/4 | BAZ15d | - |
| 3496 | 3496 | 12 | 27/8 | BAY15d | DC bayonet index |
| P21W | 17635 | 12 | 21 | BA15s | SC bayonet |
| PY21W Amber | 17638 | 12 | 21 | BAU15s | - |
| 3497 | 3497 | 12 | 27 | BA15s | SC bayonet |
| R5W | 17171 | 12 | 5 | BA15s | SC bayonet |
| R10W | 17311 | 12 | 10 | BA15s | SC bayonet |
| C5W | 17125 | 12 | 5 | SV8.5 | festoon |
| C21W | 17634 | 12 | 21 | SV8.5 | festoon |
| 2W BA7s | 17051 | 12 | 2 | BA7s | - |
| T4W | 17131 | 12 | 4 | BA9s | mini-bayonet |
| H5W | 17830 | 12 | 5 | BA9s | mini-bayonet |
| H6W | 68161 | 12 | 6 | BAX9s | - |
| H6W Long Life | 68162 | 12 | 6 | BAX9s | - |
| H21W | 68191 | 12 | 21 | BAY9s | - |

Metal Base Signal Bulbs

| | | |
|-------|-------|-------|
| 3496 | 3497 | 17916 |
| 17881 | 17635 | 17638 |
| 17171 | 17311 | 17125 |
| 17634 | 17051 | 17131 |
| 17830 | 68161 | 68162 |
| 68191 | | |




P21/5W




P21W



P21/4W




3496




3497




R5W/R10W




W3W/W5W



WY5W



H21W



T4W



2W BA7s



H5W/H6W



C21W



C5W



Candlepower Incorporated
14626 Southlawn Lane
Rockville, Maryland, USA
20850-1317

ph 301.340.0224
fax 301.762.2518
www.candlepowerinc.com